



* Tier 2 Congested Locations have been determined on Tier 1 road segments where there is excess delay. The Transportation Research Board defines excess delay as "the amount of time spent at a given location that exceeds the maximum amount of time that is generally considered acceptable."

Tier 2 Excess Delay Locations*

2004-2005 CMS Report

Figure 6

100 Clinton Square
 126 North Salina St, Suite 100
 Syracuse, NY 13202
 (315) 422-5716
 Fax: (315) 422-7753
 www.smtcmpo.org

0 2 4 Miles

0 2 4 Kilometers

This map is for presentation purposes only. The SMTC does not guarantee the accuracy or completeness of this map.



- Tier 2 Locations
- Classified Roadways
- Towns
- Villages
- City of Syracuse
- Water

Basemap Copyrighted by NYSDOT
 Data Sources: SMTC, NYSDOT, 2001
 Prepared by SMTC, 02/2005